

Roof space reflected ceiling plan - west end, 1:50 @ A1

Read with Structural Engineer's Schedule of timber repairs and Specification which refer to defects at the locations shown.



Location 1 - Truss A













